



GEM test Update

**Anand K. Dubey
for the Weizmann Group**

Some problems faced during the production with second batch of GEMS (#32 onwards).

- 6 GEMS were glued --- but all of them showed discharges in Ar/CO₂ at above 450 V. One of them (GEM #34) looked alright, but it tripped once during the pad-gain measurement.
- All these GEMS passed the intermediate checks during the stretching-gluing operations, where the leakage current tests are performed at three stages.
- this being observed in the second batch, suspicion arose whether everything was O.K. with the second batch of GEM foils.
- Reply from CERN was that ---- all GEMS were tested up to 600 V in air 35 % humidity.
- Gluing of further GEMS was halted to investigate the reasons

- Cleaned two these GEMS(GEM #36, #34) with water thoroughly. They were tested at 500 V in air at 50 % R/H. Then carried out the Fe-55 test in Ar/CO2. NOW it showed normal behaviour. No discharges observed.
- The remaining 4 modules from batch 2 will also be water cleaned.
- Based on these -- some modifications introduced in the intermediate tests performed during the module production:
 1. Any new GEM foil will first be tested upto 500 V in air in the clean room, instead of 100 V.
 2. After all resistor soldering operations, the prepared module would again be tested at 500 V to ensure that no shorts developed during the course of gluing.
- The GEM production resumed after a brief gap. Results for the two GEMS from the second batch after water treatment are shown:



Peak pulse height distribution

