Revised connector order on ROC

ROC Board Faces Downstream

Connector pair order is always J1 above J2!

Wedge 0 faces downstream as does ROC



Numbering convention

- From what I see on Hubert's test stand

- 3303 --> Wedge 3
- 3304 --> Wedge 2
- 3301 --> Wedge 1
- 3302 --> Wedge 0

Wedge 0 Final Layout



- Mating position for cable 3302
- Calibration line goes to the inside radius



Wedge 1 Final Layout





- Mating position for cable 3301
- Calibration line goes to the outside radius