

Some questions:

- *How to coordinate all changes & control from one place?*
- *How to avoid reading out strips that are not pulsed by configuring which DCM's are readout?*
- *What DAC values to use? (experience will tell)*

Outline of procedure for muTr calibration runs – MJL 12/1/00