

Online Monitoring Needs an Update

What it does now:

- Draws the ADC distribution
- Draws the HITS distribution (ADC charge per pad)
- Draws the sigma and means of post and pre pedestal

What should it do?

For the time being we have what we need, but what does the shift crew need? The shift crew just wants to know

IS THE HBD DOING OKAY?

Some ideas:

- Minimum number of events
- Standby or operational notice

Miscellanea

- Drawing is slow now, I think I can speed it up by cutting out unnecessary steps
- We have run number on each slide, anything else of this sort wanted?
- Any other comments?